

Call: **207-402-2631**

2015 CHEVROLET SILVERADO 1500 LT CREW CAB 4WD

\$27,999



131 MINOT AVE MINOT
ME,04258

[Scan QR Code or Click Here](#)



VIN: 3GCUKREH1FG182973

STK#: BL 277

EXTERIOR COLOR: BLUE

DRIVETRAIN: 4WD

TRIM: LT CREW CAB 4WD

CONDITION: USED

MPG HIGHWAY: 22

COLOR: BLUE

MILEAGE: 74600

INTERIOR COLOR: BLACK

TRANSMISSION: AUTOMATIC

ENGINE: 4.3L V6 OHV 12V

MPG CITY: 17

DESCRIPTION/OPTIONS: Very Good Condition, Full Size Crew Cab, Loaded With Many Options, Low Miles, Comes with A Plow in Excellent Condition (i will add pics of the plow soon) 4.3L V6, Automatic, 4X4 LT Trim Level with Following Options: Heated Seats, Power Seat, Power Windows, Locks, Mirrors, AM/FM, CD, USB, AUX, Bluetooth, Navigation, Chevy My Link, Auto Dimming Rear View Mirror, Automatic Climate Control, Dual Climate Control, Cruise Control, Steering Wheel Controls, Heated Rear Window Running Boards, Bed Liner, Tri-Fold Tonneau Cover, Alloy Wheels, Fog Lights, Keyless Entry, Remote Start, Trailer Tow Package Including Electric Brake Controller, Plow Package (everything is there, push plates, wiring, controller, and plow) Brand New Front Struts, Alignment, Newer Brakes and Rotors, Newer Tires, Fully Serviced, All Fluids Replaced, Entire Truck was treated with a rust preventative oil undercoating (rockers, cab corners, bed sides, frame inside and out) Only 74,600 Miles Comes with a 30 day warranty 30 day temp plate and brand new inspection sticker Asking \$28,000 with plow Call or Text 207-402-2631 This truck will have a repaired/ rebuilt Title. A tree fell across the Left fender and hood and it caused the curtain air bags to deploy. We replaced the parts with good used ones the same color from another truck. I have photos of the damage. No frame or Engine Damage, no damage to the cab. All repair work was professionally done and is guaranteed.

Child Safety Door Locks	Locking Pickup Truck Tailgate	Power Door Locks	4WD/AWD
ABS Brakes	Electronic Brake Assistance	Traction Control	Vehicle Stability Control System
Driver Airbag	Passenger Airbag	Side Head Curtain Airbag	Second Row Side Airbag
Air Conditioning	Cruise Control	Tachometer	Tilt Steering
Tilt Steering Column	Leather Steering Wheel	Steering Wheel Mounted Controls	Tire Pressure Monitor
Trip Computer	AM/FM Radio	Navigation Aid	Telematics System
Front Split Bench Seat	Second Row Folding Seat	Cargo Area Tiedowns	Automatic Headlights
Daytime Running Lights	Pickup Truck Cargo Box Light	Alloy Wheels	Full Size Spare Tire
Run Flat Tires	Power Windows	Deep Tinted Glass	Interval Wipers

B & L Autos



© 2022 AutoDrivenMarketing.com